INITIAL TSMA INSPECTION REVIEW

INSPECTED BY: KCA **LOCATION:** SR13 San Jose Blvd at Orange Picker Rd

DATE: 10/19/2020 **FIN. PROJ. NO.** 432396-1-52-01

TSMA NUMBER	DEFICIENCIES NOTED DURING 90% HMLP INSPECTION	CORRECTION REVIEW REPAIRED YES / NO (NO REQUIRES COMMENT UNDER DEFICIENCY)
72M509	**Element 8480 –**	
	All foundations: Structural grout pads have vertical cracks up to full height x 1/64in. wide. (See photo 1)	Yes
	Element 8481 –	
	No deficiencies observed.	
	Element 8484 –	No. Line believed to be a JEA Fiber Temporary Line. Lou Flemming JEA contacted. Line to be relocated January 2021.
	H2: There is a utility line in contact with the top face approximately 6ft. from the moment connection. (See photo 2)	
	H3: There is a utility line in contact with the south traffic signal. (See photo 2)	No. Line believed to be a JEA Fiber Temporary Line. Lou Flemming JEA contacted. Line to be relocated January 2021.

Please designate either FDOT or CEI.

Deficiencies corrected and approved by: William Wortner Digitally signed by William Wortner Date: 2020.12.09 08:31:36 -05'00' **(FDOT Project Engineer or CEI Project Engineer), on** _____ **indicates structure is ready for acceptance by Maintenance.**

(Date)

Form/90% Bridge Inspection.doc.05/28/08

INITIAL TSMA INSPECTION REVIEW

TSMA NO. 72M509

INSPECTED BY: KCA PROJECT LOCATION: **SR13 San Jose Blvd at Orange Picker Rd**

DATE: 10/19/2020 **FIN. PROJ. NO. 432396-1-52-01**



Intersection Sketch

INITIAL TSMA INSPECTION REVIEW

TSMA NO. 72M509

INSPECTED BY: KCA PROJECT LOCATION: **SR13 San Jose Blvd at Orange Picker Rd**

DATE: 10/19/2020 **FIN. PROJ. NO. 432396-1-52-01**

Photo 1 – Vertical crack in F3 grout pad

Photo 2 – Utility line in contact with H2 and the south traffic light at H3