

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson


ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)		
		Yes/No Initials	Not in Scope	
SE Corner of Ricky Rd. Bicycle shop parking lot	<p>Parking stops (2) broken and removed during drilled shaft installation.</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>Community Center at Orange Pickers Rd.</p>		<p>Remove construction material and debris. Reestablish sod in front and side yard of center.</p> <p>Contractor Seeded Area.</p>	<p align="center">YES / NO</p> <p align="center">YES <input checked="" type="checkbox"/></p> <p align="center">No <input type="checkbox"/></p>		
------------------------------------------------------	-----------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson



ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)		DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
			REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)		
			Yes/No Initials	Not in Scope	
NW corner of Mandarin Rd.		Remove all construction debris and fencing 	YES / NO		
			YES <input checked="" type="checkbox"/>		
			No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

**SE corner
of Julington
Creek Rd.**



Remove all construction debris and trash



YES / NO

YES



No



Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson



ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)	Yes/No Initials	Not in Scope
SW corner of Westberry Rd.	 <p>Regrade and sod where broken down backhoe was removed</p> 	YES / NO YES <input checked="" type="checkbox"/> No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>Julington Creek Rd NW corner</p>		<p>Repair rail that was previously removed by FSC</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		
----------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson


ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)		
		Yes/No Initials	Not in Scope	
Julington Creek Rd at Sta.55+50 Rt BL Const.	Replace concrete sidewalk 	YES / NO YES <input checked="" type="checkbox"/> No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>Westberry Rd. at Sta.69+50 Rt BI Const</p>		<p>Replace concrete sidewalk</p> 	<p align="center">YES / NO</p> <p align="center">YES <input checked="" type="checkbox"/></p> <p align="center">No <input type="checkbox"/></p>		
------------------------------------------------------	-----------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson


ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)		DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
			REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)	Yes/No Initials	Not in Scope
Marbon Rd. at SE corner		<p>Replace bushes that were removed for drilled shaft installation</p> <p>Property is FDOT R-O-W and bush replacement not required.</p>	<p>YES / NO</p> <p>YES <input type="checkbox"/></p> <p>No <input checked="" type="checkbox"/></p>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson


ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)		
		Yes/No Initials	Not in Scope	
SE corner of Marbon Rd	<p>Sod replacement</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>NE corner of Julington Creek</p>		<p>Sod replacement</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		
----------------------------------------------------	-----------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson



ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)		DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
			REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY) Yes/No Initials	Not in Scope	
NE corner of Julington Creek		Concrete debris new to be removed 	YES / NO YES <input checked="" type="checkbox"/> No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p><u>NE corner of Ricky Rd.</u></p>		<p>Sod replacement</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		
---------------------------------------------	-----------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson



ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY)	Yes/No Initials	Not in Scope
SW corner of Marbon Rd.	 <p>Utility box needs replaced and adjusted. Concrete sidewalk needs to be completed</p> 	YES / NO YES <input checked="" type="checkbox"/> No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

DATE REINSPECTED: December 2, 2020

--	--	--	--	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>Westberry Rd. at Sta.72+40 Lt BI Const</p>			<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		
------------------------------------------------------	-----------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	--	--

			CORRECTION REVIEW
--	--	--	--------------------------

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson


ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)		DEFICIENCIES NOTED DURING % INSPECTION	REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY) Yes/No Not in Scope Initials		
All (7) intersection between Julington Creek and Mandarin Rd		Finish striping for crosswalks and gore area at Julington Creek and stop bar at Ricky Rd.	YES / NO YES <input checked="" type="checkbox"/> No <input type="checkbox"/>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>San Jose Blvd and I-295 Easbound on ramp lay down area</p>		<p>Minor construction material and debris needs to be removed</p> <p>Area determined to be an old lay down yard from contractor prince for contract E2S01. Not related to this project.</p>	<p>YES / NO</p> <p>YES <input type="checkbox"/></p> <p>No <input checked="" type="checkbox"/></p>		
----------------------------------------------------------------------	-----------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	--	--

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

Location (Sta. Number)	DEFICIENCIES NOTED DURING % INSPECTION	CORRECTION REVIEW		
		REPAIRED YES/NO (NO REQUIRES COMMENT UNDER DEFICIENCY) Yes/No Initials	Not in Scope	
<p>San Jose Blvd and I-295 Easbound on ramp lay down area</p> 	<p>Removal of Porta-potty</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson



ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

DATE REINSPECTED: December 2, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

<p>NW corner of Marbon Rd.</p>		<p>Added to list after sidewalk and curb concrete pour. Sod needed</p> 	<p>YES / NO</p> <p>YES <input checked="" type="checkbox"/></p> <p>No <input type="checkbox"/></p>		
---------------------------------------	-----------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	--	--

			CORRECTION REVIEW
--	--	--	--------------------------

Preliminary Inspection San Jose Blvd between Mandarin Rd. and Julington Creek Rd.

INSPECTED BY: Jason Chisholm/David Jefferson

ROAD SECTION NUMBER: SR 13

LOCATION: Mandarin Rd. south to Julington Creek Rd.

DATE INSPECTED: October 13, 2020

PROJECT NO: E2X65 - Fin. No. 432396-1-52-01

DATE REINSPECTED: December 2, 2020

Location (Sta. Number)		DEFICIENCIES NOTED DURING % INSPECTION	REPAIRED YES / NO (NO REQUIRES COMMENT UNDER DEFICIENCY) <small>Yes/No Not in Scope Initials</small>		
			YES / NO YES <input type="checkbox"/> No <input type="checkbox"/>		
			YES / NO YES <input type="checkbox"/> No <input type="checkbox"/>		